

	DUTY ON WHICH ENGAGED: Solo Flying Practice NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot completely stalled A/C at 10 ft. when flattening out to land on aerodrome causing aircraft to dive into the ground and turn over on its back.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Commanding Officers Report: DATE: 10-2-41 COMPOSITION: (H.C. Johnson) Flight Lieutenant. AOC/POC/PSF/R/N RECOMMENDATIONS: 1100-40-18 (DTPR)	manufacture of the contract of
	PRIMARY CAUSE: Error of judgment on the part of the pupil, through inexperience.	In view of para. 3 of the attached covering letter from No. 2 Training Command, it is considered that arinquiry should be made as to why this pilot was passed as medically fit in the first instance. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
・)・) ・・	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Pupil wore eye goggles for the first time.	RECORDED BY DATE CHECKED BY DATE CHECKED BY DATE O O O O O O O O O O O O O O O O O O O	