

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
DUTY ON WHICH ENGAGED: COURT OF INQU	UIRY, INVESTIGATING OFFICER
	NG OFFICER'S REPORT:
Airport to Stanley, N.S. NATURE OF ACCIDENT AND STAGE OF FLIGHT: COMPOSITION:	Commanding Officers Report. 14-3-41
Due to the 20 m.p.n. south-west	Wing Commander (W. W. Durana)
wind, it caused the a/c to drift strongly to the right. The pilot was unable to keep the a/c straight and ran into a six foot snowbank on the right side of the runway, and turned on its back.	Wing Commander (W.W. Brown.) L5/P55/WWC/
Strong cross-wind, together with icy surface of runway pushed the aircraft into the snowbank. ACTION TAKEN:	-
(A) DISCIPLII	NARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Error on part of pilot due to	
inexperience on light aircraft	RECORDED BY DATE
	CHECKED BY DATE
))))))))))))))	