

Γ	()))))))))))))))))))	/ ɔ
()	DUTY ON WHICH ENGAGED: PRACTICING COURT OF INQUIRY, INVESTIGATING OFFICER	اسد و
)	FORCED LANDING. OR COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: LOW GLIDING SPEED IN A TURN RESULTING COMPOSITION: COMPOS)
)	IN A SPIN. THE AIRERAFT WAS FLYING AT ABOUT 3500 WHEN THE PILOT PUT THE AIRCRAFT INTO A SPIN; SET THE CONTROLS TO COME OUT OF THE SPIN, AND THE AIRCRAFT CAME OUT OF THE SPIN AT ABOUT SPIN; SET THE CONTROLS TO COME OUT OF THE SPIN, AND THE AIRCRAFT CAME OUT OF THE SPIN AT ABOUT FLYING OFFICER SHARPE E.W.C.	
)	3006FT. THE PILOT THEN ATTEMPTED TO FLATTEN OUT, RECOMMENDATIONS: BUT THE AIRCRAFT DID NOT RESPOND. MORE INSTRUCTION WITH RESPECT TO SPIRALS, SPINS, AND PARTICULARLY FLAT SPINS.) 3
)	FAILURE OF PILOT TO MAKE PROPER RECOVERY FROM A DELIBERATE SPIN. ACTION TAKEN:)
う	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	. 1
ううい	THE AIRCRAFT FELL INTO A SPIRAL FOLLOWING THE SPIN ANDIN THAT MANNER LOST CONSODERABLE HEIGHT BEFORE RECOVERY WAS MADE TO A STRAIGHT GLIDE.)
) —))))))))))))))))))))