

	Dual Instruction Flight NATURE OF ACCIDENT AND STAGE OF FLIGHT: While attempting an approach and landing, the final approach was high, the aircraft stalled and settled heavily on the undercarriage damaging the left oleo shock leg and left wing tip.	COURT OF INQUIRY, INVESTIGATING OFFICER. OR COMMANDING OFFICER'S REPORT: Commanding Officer's Report 26-3-41 COMPOSITION: E.A. Weaver, Flight Lieutenant LH/PSHH/L/USH RECOMMENDATIONS: It is recommended that instructors pay close attention at all times to ab initio pupils and apply corrective
)))	PRIMARY CAUSE: Error in judgment on the part of both pupil and instructor.	measures at once when errors in judgment are made.
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
)	Instructor failed to open the throttle quickly enough and the aircraft struck the ground.	RECORDED BY DATE
)) 		O O O O O O O O O O O O O O O O O O O