

NATURE OF ACCIDENT AND STAGE OF FLIGHT: R7445 WAS TAXILED INTO REAR OF R7448	OR COMMANDING OFFICER'S REPORT: Monthly Accident Report. MULT April.
R7445 did not see a Battle	OR COMMANDING OFFICER'S REPORT: Monthly Accident Report. April. TCA/RCT TCA/XA
taxiing immediately ahead of him, mistaking his lights for a boundary marker. He callided with the tail of RIMARY CAUSE this aircraft R7448.	RECOMMENDATIONS: An assistant aerodrome control officer to operate at one end of the landing runway, to work in conjunction with the Aerodrome Control Officer.
Failure on the part of P/O Bradley to observe Battle taxiing on the same runway and in the same direction	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
at night.	Pilot Officer Bradley was suspended from flying instruction.
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECORDED BY DATE