

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
SEQUENCE - SWINGING PROPELLOR TO START	OR COMMANDING OFFICER'S REPORT:
AIRCRAFT. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: MONTHLY ACCIDENT RETURN.
LEG INJURY TO CIVILIAN ENGINEER.	COMPOSITION:
ENGINE STARTING THROUGH MISUNDERSTANDING.	• •
	·
	RECOMMENDATIONS:
	INSTRUCTIONS FOR RE-PROP SWINGING GIVEN
PRIMARY CAUSE:	STUDENTS AND GROUND CREW.
AIRCRAFT HOOD BEING CLOSED.	
NAME TO SETTING SESSES	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
DECOMPANT CAUSE ON CONTRIBUTING FACTORS.	
ENGINE STARTED THROUGH MISUNDERSTANDING OF COMMANDS.	RECORDED BY DATE
	CHECKED BY DATE