

1	(5))))J)))))	· · · · · · · · · · · · · · · · · · ·	111
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY,	INVESTIGATING OFF	TCO/PCT/UBF	3 3 3 3
)	Circuits & Landings at Night.	OR COMMANDING O	FFICER'S REPORT:	TCO/PCT/UBF	3
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	Monthly Accie	ent Return.	,
)	Completed solo night circuit	COMPOSITION:	•		
)	and was taxiing back to the taxiing				-
)	post at slow speed. His brake pres low and was unable to stop the a/c	sure was			÷ 9
)		RECOMMENDATIONS	<u>:</u>		•
)	servicing lorry at the taxiing post	•			J
·)	PRIMARY CAUSE:				⇒
·)	Failure of brake pressure)
ر ۱					3
)		ACTION TAKEN:			3
,			(B) TECHNICAL (C)	OTHER	Э
))					3
,				·)
<i>)</i>	CECONDADY GLUCT OF CONTROL OF			•)
<i>)</i>	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Colliding with stationary servicing)
)	lorry at the taxiing post.			RECORDED BY	DATE)
)	18. 188			e.)
(ر	Ψ;			CHECKED BY	DATE
)))))))))))))) j