

```
DUTY ON WHICH ENGAGED:
                                       COURT OF INQUIRY, INVESTIGATING OFFICER
                                       OR COMMANDING OFFICER'S REPORT: ILCO/POL/PCL
Force landing instruction.
                                                    Commanding Officer's Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT
                                       DATE:
Port wing struck top of tree while
                                       COMPOSITION:
                                                    H.C. Ledoux, Flight Lieutenant.
aircraft climbing after force. In-
structor demonstrating forced land-
ing to pupil and carried out success-
ful forced landing approach, open-
                                       RECOMMENDATIONS:
ing the throttle at about 40 ft.
above ground. After port wing struck
PRIMARY CAUSE tree, aircraft crashed.
Lack of sufficient observation for
obstacles on part of instructor.
Carelessness
                                       ACTION TAKEN:
                                         (A) DISCIPLINARY (B) TECHNICAL
                                       All instructors warned to keep sharper lookout
                                       especially while talking into mouthpiece. The in-
                                       structor concerned was given a personal admonition.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
Aircraft struck top branches of tree.
                                                                     RECORDED BY
                                                                                          DATE
                                                                     CHECKED BY
```