

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Bombing exercise.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Re turn.
Forced landing executed at 6000' when motor failed. Normal procedur for forced landings carried out.	EB/AOP/ES/MOSE
	RECOMMENDATIONS:
PRIMARY CAUSE:	
Failure of engine due to broken connecting rod.	
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
	RECORDED BY DATE
	CHECKED BY DATE