

OUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
CHECKING RADIO EQUIPMENT	OR COMMANDING OFFICER'S REPORT: R.170
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
AIRCRAFT TURNED ON ITS BACK AFTER LANDING	COMPOSITION: LM/ATO/PEM/JBP
	DECOMMENDATIONS.
	RECOMMENDATIONS:
PRIMARY CAUSE:	
Aircraft nosed over following landing.	
	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
	All pilots instructed of too harsh application
	of brakes .
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Poor flying technique on the pa	
of the pilot in that the aircraf	t manufacture and the second s
was allowed to land in tail up p	osition