

| DUTY ON WHICH ENGAGED: | COURT OF INQUIRY, INVESTIGATING OFFICER |
|---|---|
| Aerobatic Practice. NATURE OF ACCIDENT AND STAGE OF FLIGHT: | OR COMMANDING OFFICER'S REPORT: 14 O C POC PSF/B/N/POM DATE: COURT OF INQUIRY |
| Aircraft crashed into barn. PILOT APPRENTLY ATTEMPTING FORCED LANDING OUTSIDE OF AUTHORIZED SORO AREA DE | Squadron Leader L.G.G.J. Archambault Flight Lieutenant P.E. David Flying Officer G. Minard. |
| | RECOMMENDATIONS: Disciplinary action should be taken against the pilot |
| PRIMARY CAUSE: Stalled in steep turn and slipped into the ground from about 100 ft. | The maintanance regulations should be more closely followed by the Civilian Company. |
| | ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER |
| SECONDARY CAUSE OR CONTRIBUTING FACTORS: | |