

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	33333333333333333333333333333333333333
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
FLYING INSTRUCTION	OR COMMANDING OFFICER'S REPORT:
NATEDE OF ACCIDENT AND OTAGE OF FUGUE	COURT OF INQUIRY
NATURE OF ACCIDENT AND STAGE OF FLIGHT: AIRCRAFT CRASHED IN LARGE OPEN FIELD	DATE: 13-7-41
AIRCRAFT CRASHED IN LARGE OPEN FIELD AIRCRAFT WAS PREFORMING AEROBATICS, DOING	SQUADRON LEADER HOLMS C. J. H. (C435)
LOOPS AND ROLLS AT AN ALTITUDE OF APPROX-	FLIGHT LIEUTENANT UPSON C.C. (C712)
MATELY 2000 AND LOWER, ACCORDING TO CIVILIAN	FLYING OFFICER LIVERMORE R.R. (C896)
EYE WITNESS. AIRCRAFT STALLED IN AN INVERTED	RECOMMENDATIONS: 10C/AOC/PSF/B/N
POSITION, WENT INTO A SPIN AND CRASHED INTO A	10C/HOC/1 SI JEJI
FIELD AT APPROX. L7850 HRS. PRIMARY CAUSE:	
,	
Failure to recover from spin resulting in impact with the	
ground	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Performance of aerobatics at	
a height not considernt with	RECORDED BY DATE
safety	
	CHECKED BY DATE
)	77777777777777