

HB 140

BEECHCRAFT UC45 EXPEDITER E3T

1944

T E TRANSPORT.

43-35553

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
25/11/50	check valve repairs	a/c Industries	501665				
18 Oct 51	reconditioning of motor - 1 modification of gear RMI-27	MBA	511761			13/8/52	ADC
22 Mar 54	Retrofit mod	MBA	51376816			7 May 54	SR & P
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

1332 21 Jan 47 - parts equipped - SCR 2741 and SCR 2694. on file
1038 Ju 48. (Bentley)

25 Sep 47 - a/c #47 - 1937 - 744.550 - TSO. No. 2120. 5th.

231 Oct 47 - a/c #47 - 1937 - 1864.15. Filament Ltd. (Consolidation) (UK)

15 Mar 48. 1957. 1

31 Mar 49 - a/c #47 - TSO. 2277.0. TSO. 2277.4

HB 140

EXPEDITER
3TWASP
R985-AN14B

43-35553 2

215127 21750

RCÁF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
7 May 54	QTO-1101	^{Flight School} Serviceable Remount Shop			
16 Apr 57	436	TC 102 RD Trenton			
4 Jun 59	TC Qto 25	TC UEFIS Trenton			
10 Aug. 59	Tc Qto 41	Tc. FIS Moose Jaw			
16 Nov 60	QTO731	DR Lincoln Park ^{LTS}			
13 Jun 61	299	11754 Timmins AFB			
15 Jan 62	857	WR 6 RD			
6 Feb 62	916	WR 6 RD Denville			
19 Mar 62	1030	1030 London			
19 Mar 62	1029	Mutual aid Free France France			

C103214-100 (SAC/ACR 2-1) 4 Feb 61 Tentative selected for partial to Mutual Aid
 selected as a support aircraft

