

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
18.11.41	"C"	Windsor Aerod.	1700	TEFTSs A97	14/11	Sgt. G. Almas	1		
7.12	"C"	Maidstone Township	1420	TEFTSs A102	8/12	Sgt. G. Almas	1		
7.3.42	"B"	Windsor Aerod.	1825	TEFTSs A23	8/3	Sgt. Calmas	1	Write off	
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc. 3: After landing at 4109 swung and collided with 4502 which had stopped. Eng. installed 1651/6300

REMARKS:

Involved in crash at Windsor 7.3.42

RECORD OF WRITE-OFF							
APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
6RD (9107)	6.4.42	10382-4502	6.5.42	SASO ² 17C	CO 6RD	8.5.42	C319
DISPOSAL PARTICULARS							
AIRFRAME To be reduced to spares and produce							T. O. No. 13.5.42
ENGINE/S (QUOTE SERIAL NOS.)							T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)							
ACCESSORIES							
REMARKS:							EFFECTIVE DATE WRITTEN-OFF 13.5.42

AIRCRAFT RECORD CARD

FIRST ENTRY AT #1 Training Command	DATE 9/7/40	TRANSFER ORDER NO. 734			
TRANSFERS		TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
8.5.42	To spares & produce	T.O. C319			

REMARKS

ENGINE TYPE KINNER B5R	UNITS 1	AIRSCREW TYPE (CODE) 1200-38-3	REF. No.
BATCH No.	QUAN. IN BATCH 1	LEDGER FOLIO	SPECIFICATION No.
REGISTRATION No.	MAKE & MODEL (DATE OF)	YEAR 1940	MANUFACTURERS No.
		ELEM TRAINER	