

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
15/1/41	"A"	Windsor Airport	1000	#7 EFTS, Sig 25	15/1	2/Lt. H. Fairweather	1	WRITE OFF	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

Re Acc. 1 - Failure to recover from inverted spin.  
 Total flying time: - 314 hrs (auth. ITC, 926 22 1, d, 22/9-42)

