

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

GUNNERY EXERCISE

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

HYDRAULIC LINE BROKE ON TAKEOFF CAUSING
PILOT TO FORCE LANDING WITH WHEELS
RETRACTED

LUC / 1000W / UDM

RECOMMENDATIONS:

UCDE

PRIMARY CAUSE:

HYDRAULIC LINE BROKE

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilots have been warned that if a hydraulic line breaks the immediate action is to raise the seat to its highest extent put the head out in the slipstream, turn crank and lower the wheels.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT FORCE LANDED WITH UNDERCARRIAGE
RETRACTED

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____