

	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)
,	GUNNERY EXERCISE.	OR COMMANDING OFFICER'S REPORT: Monthly Accident Return.	}
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: STARBOARD TIRE BEEN OUT AFTER TAKE-OFF. PILOT ATTEMPTED A NORMAL THREE-POINT LANDING ON THE TURF, TO THE LEFT OF AND PARALLEL TO NO. 1	DATE: COMPOSITION:)
	RUNWAY. THE MACHINE TOUCHED DOWN SLIGHTLY TOO SOON, BEFORE THE TAIL WAS FULLY DOWN. THE MACHINE SWERVED TO THE RIGHT SHORTLY AFTER IMPACT AND THE PILOT WAS UNABLE TO HOLD IT ON A STRAIGHT COURSE PARTIAL GROUND LOOP RESULTED. U/C PRIMARY CAUSE COLLAPSED.))
	GROUND LOOP ON LANDING DUE TO DEFECTIVE TIRE.)
		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER) ラ)
ŀ)) SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
	GROUND LOOP CAUSED U/C TO COLLAPSE.	RECORDED BY DATE)
))))))))))))))))	CHECKED BY DATE)))))))))))))))))))