

| 1 | | |
|----------|---|--|
| () | DUTY ON WHICH ENGAGED: | COURT OF INQUIRY, INVESTIGATING OFFICER |
|) | Sequences 6-7-9-16. | OR COMMANDING OFFICER'S REPORT: |
|) | NATURE OF ACCIDENT AND STAGE OF FLIGHT: ON LANSING OVER COPRECTED GROUND LOOP CAUSING GROUND LOOP. Applied correct rudder to recover but failed to | Monthly Accident Return. DATE: COMPOSITION: |
|) | centralize the rudder in time and ground looped in other direction. | RECOMMENDATIONS: |
|) | | |
|) | PRIMARY CAUSE: | |
|) | GROUND LOOP - INEXPERIENCE. | |
|) | | ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER |
|) | | Log Book entry. Lecture by C.F.I. Dual only off runways. |
| , | SECONDARY CAUSE OR CONTRIBUTING FACTORS: | • |
| , | Lack of wind direction indication. | |
| , | | RECORDED BY DATE |
|)) | | CHECKED BY DATE |