

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Practising sequences 7-912.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Return R 170.
Pupil pilot was taxiing out from	COMPOSITION:
tarmac in Fleet 4642, caught his foot in brake and opened throttle instead of closing it. He collided with fleet 4735.	RECOMMENDATIONS:
PRIMARY CAUSE:	
Poorly executed taxiing manoeuvre.	
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	PP admonished Entry in Log Book.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft taxied into a second aircraft.	RECORDED BY DATE
	CHECKED BY DAT