

DUTY ON WHICH ENGAGED:

Flying Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil landed into wind opened throttle to go round again went into steep climbing turn to right stalled striking ground with starboard main plane.

COMPOSITION:

000/R/000/PSE/0/N

RECOMMENDATIONS:

Pupil is being tested by Chief Flying Instructor as to suitability for continued training.

PRIMARY CAUSE:

Inexperience of pupil pilot
Pilot opened throttle to go around again, swung right into ground.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil landed into wind and opened throttle, but failed to check swing.

RECORDED BY

DATE

CHECKED BY

DATE