

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Solo forced landing practice.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION:	
Insufficient correction for drift	COMPOSITION:	
ground loop causing aircraft to stand on nose.		
scand on nose.		
	RECOMMENDATIONS:	
PRIMARY CAUSE:		
TRIMART CAUSE.		
Inexperience on the next of the		
Inexperience on the part of the pilot in cross wind landing.		
Inexperience on the part of the pilot in cross wind landing.		
	ACTION TAKEN:	
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
pilot in cross wind landing.  SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
pilot in cross wind landing.  SECONDARY CAUSE OR CONTRIBUTING FACTORS:		DATE
pilot in cross wind landing.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	DATE