1	AFO WE A SE	////	5 24 23 22		/ /	8 17 0 15 (14 13 15 140 15 15 140 15 15 140 15 15 15 15 15 15 15 15 15 15 15 15 15	ALT FUEL		9 8	2 2 20	6 S LNG	A 3 2 Chis A R R R R R R R R R R R R R R R R R R
Ų	PILOT	OTHERS			FRAME	FAIL				ENG		FAIL		
ĮĮ.	CAUSES OF ACCIDENTS UNIT & FFTC COM. PLACE DATE TIME									Thurs of				
PE 0	UNIT # I E.F.T.S. COM. MALTON ONTARIO				AERODROME					H.Q. FILE 1100-43-75				1 1 / 6.7
1	A/C TYPE TIGER MOTH NAME RA			No. 4375			CRASH CAT. C-6						NIGHT	S WERT
L				NK	No.	DUTY	INJURI			ES		SERIOUS		> DRY JRY
E	COOPER G.S. LAC				1313990 P UNINJURED.						FATAL.	YAULNI		
E OF ENGIN												CAF SERIA		O TO O T
TYPE	TYPE A/F EXTENT				REPORT SERIAL			HOUSE FLOWN BY BUILDIE						1 1 1/8/
	& ENGINE	No.	OF DAMAGE	FORM	No.	DAT	·	NIGHT	ON T			TAL	LAST	
	Мотн	4375	SLIGHT				11131	, NIGHT	DUAL	SOLO	DUAL	SOLO	6 MOS.	1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
۲×	MAJOR	7375	NIL					-	15	4	15	14		15101/3/
EGO	10.00 ·													
CATE	SIGNAL NO		UNIT NO. & DA		сом.	No. & E	ATE	REPO	RT	F	LE	DA	ATE	
\angle	, , , , ,		<u> </u>	I A T	URE	O F	ACCI							
./	2/3/4/	6/6/1/	6/0/0/:	/2/	/3/10/	\\$/\\$	/1/0/	/3/v)	/ v / v	2/23/	/2ª/2	5/20/	1/2	0/20/30/2

DUTY ON WHICH ENGAGED:		COURT OF INQUIRY, INV		CER	
PRACTISING SEQUNCES 6-7	-9-16-17	OR COMMANDING OFFIC	ER'S REPORT: R 170		
NATURE OF ACCIDENT AND ON LANDING INTO WIND THE		DATE: COMPOSITION:	LAS	5/4/2/2011	
TWICE. THE THROTTLE WAS	· · · · · · · · · · · · · · · · · · ·		ŕ	,	
AIRCRAFT TOUCHED ON THE		PED			
TO THE RIGHT COLLAPSING	THE UNDERCARRIAGE.	RECOMMENDATIONS:			
			NIL		
PRIMARY CAUSE:		•			
ERROR ON THE PART OF THE	PILOT DUE TO				
INEXPERIENCE.					
		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C)	OTHER	
		PILOT GIVEN MORE DUAL ENDORSED, AND AWARDED		ARADED, HAD HIS LOG BOOK	
•					
SECONDARY CAUSE OR CON	TRIBUTING FACTORS:				
GROUND LOOP					
				RECORDED BY	DATE
				CHECKED BY	DATE