

, , , , , , , , , , , , , , , , , , , ,	
UTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
OUTUAL INSTRUCTIONAL FLIGHT.	OR COMMANDING OFFICER'S REPORT:
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: NOVEMBER 6TH, L94L.
LOCALET OVERTHANES LANDING ON COST COOLING	COMPOSITION:
IRCRAFT OVERTURNED LANDING ON SOFT GROUND.	
	RECOMMENDATIONS:

RIMARY CAUSE:	Nil
ERROR JUDGMENT OVERSHOT RAN INTO SOFT GROUND.	
	ACTION TAKEN
	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
	Endorsement of Pilot Officer Darragh's log boom in accordance with C.A.P. 100.
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft turned over on its back.	
	RÉCORDED BY DATE
	CHECKED BY DATE