

)		
(,)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)
()	Cross country flight.	OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION: FB/70P/1 S/00/10/10/10/10/10/10/10/10/10/10/10/10/
)	Forced landing - overshot field - propellor broken.	COMPOSITION:
).)
)		RECOMMENDATIONS:
)		
)	PRIMARY CAUSE:	
)	Engine failure due to severe icing.	•
))
)		ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
) ()		QUITE ABNORMAL CONDITIONS. PILOTS TOLD TO LAND IN FUTURE UNDER SIMILAR CIRCUMSTANCES.
)		
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	· ,
)	NO SUITABLE LANDING GROUND WITHIN GLIDING DIST.	ANCE, RECORDED BY DATE
)	AND AIRCRAFT HIT RIDGE STOOD ON NOSE AND BROKE	ALCONDED BY
,	PROPELLOR.	CHECKED BY DATE
)		