

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Wight circuits and landings.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
100 SAA	COMPOSITION: LM/JINT/PC M/USP
Pilot applied brakes harshly during	LOUIN IN CYCEP
night landing. Aircraft tipped up	
on nose.	RECOMMENDATIONS:
PRIMARY CAUSE:	Nil
Excessive use of brakes.	
and the second second	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Nil
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft tipped up on nose.	RECORDED BY DATE
	CHECKED BY DATE
(