

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Familiarization flight. OR COMMANDING OFFICER'S REPORT: Court of Enquiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 11TH NOVEMBER, 1941 ) Force of impact on landing caused COMPOSITION: aircraft to split in two and burst President Blackburn, A.P. (C.846)into flame. Member FL.Lt. Atkinson, M.R. (39364) Member P/0Coggon, A.F. (J.3495)RECOMMENDATIONS: That Pilots who have not had previous experience as instructers, should not be used to give a conversion course to a pupil with no experience on PRIMARY CAUSE: the type. Loss of flying speed. Aircraft (b) That Pilots posted to this Detachment, who are stalled 40 feet above runway. unfamiliar with Lysander Aircraft, be trained on a Error in judgment on the part of ACTION TAKEN: less hazardous neighbouring Aerodrome. whe Pilot. (A) DISCIPLINARY (B) TECHNICAL (C) OTHER No disciplinary action is contemplated with the result of this accident, as all Air Regulations and previous instructions were carried out with all the necessary measure of safety, and under the strict supervision and personal observance of the Commanding SECONDARY CAUSE OR CONTRIBUTING FACTORS: Officer. Aircraft crashed and burst into flames. RECORDED BY DATE CHECKED BY DATE