

			/)
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFF	ICER)
) PRACTICING LANDINGS.	OR COMMANDING OFFICER'S REPORT:	<u>r170</u>	
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:) WHILE STUDENT WAS MAKING A POWER APPROACH	DATE: COMPOSITION: LH/23	11-)
HE LANDED HARD ON WHEELS AND BOUNCED CORRECT- ING FOR BOUNCE BY OPENING THROTTLE BUT FAILED	·)
) TO MOVE CONTROL COLUMN FORWARD SUFFICIENTLY TO) MAINTAIN FLYING SPEED. AIRCRAFT THEN STALLED DROPPING ON RIGHT WING AND TURNING UP ON NOSE	RECOMMENDATIONS:)
) AND THEN ON TO LEFT WING FINALLY DROPPING DOWN HA) PRIMARY CAUSE: ON TAIL WHEEL.	N11)
LACK OF EXPERIENCES and by a slight cross-wind condition.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OT	HER)
	Nil)
) SECONDARY CAUSE OR CONTRIBUTING FACTORS: Starboard wing tip struck the)
ground.		RECORDED BY DATE	,
)		CHECKED BY DATE	ز
		, , , , , , , , , , , , , , , , , , ,	. 1