

DUTY ON WHICH ENGAGED: Solo practice.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Struck another aircraft while taxis	DATE: COMPOSITION:  TO A PCT
Pupil increased R.P.M.'s to assist turning the aircraft. Turned too fast and struck another aircraft.	In MAJXA  RECOMMENDATIONS:
PRIMARY CAUSE:	Bil
Pupil turned too fast.	
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Personal admonition. Pupil's log book endorsed.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft swung into another machine	RECORDED BY DATE
	CHECKED BY DATE