

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER		
Dual instruction.	OR COMMANDING OFFICER'S REPORT	<u>R170</u>	
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: LU/	-)
) Misjudged landing hit mud. Aircra	£t COMPOSITION:)
) overturned. Two aircraft ahead of	him)
, were landing quite a distance up t	the		,
runway. There was enough room for	the RECOMMENDATIONS:		
aircraft to land behind and to the	right)
of the aircraft ahead. Apparently watching the ground and the a/c at	he was Nil		
time and the wheels hit just short	of the runway.)
) Undershot runney.	o_ one a directly .		
Primary Cause.			`
	ACTION TAKEN:)
Undershot runway.	(A) Disciplinary (B) Technical (C	O OTHER)
$\mathcal{O}(\mathcal{O}_{\mathcal{C}})$	Admondation of the Second)
) 3 (4) (5)	Admonished Log book	k endorsed.)
, 2. Underskat			,
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:			,
) Aircraft hit soft mud just short	of		
Funway.		RECORDED BY	DATE
)		CHECKED BY	DATE)
· · · · · · ·))))))))))))))))))