

, , , , , , , , , , , , , ,	
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Collection of Ferry Pilots on	OR COMMANDING OFFICER'S REPORT: Court of Inquiry
completion of their duty.  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  A/C left Weyburn, Sask. for Wpg.,  Man. No weather report was obta- ined. A/C was seen in the vicinity of McGregor, where witnesses state evidence that engines were not oper	DATE: COMPOSITION:
	Pres. Wg. Cmdr. T.C. Dickens RAF 16243 33 SFTS., RAF, Mem. Flt. Lt. H.R. Patton 8 Repair Depot, RCAI
ting properly. Aircraft stalled and dove into the ground.  FRIMARY CAUSE:	For further recommendations and conclusions see File 1700-7841 para 5, page 44 (i).
Obscure-	,
	)
23 Nat Laoun	ACTION TAYEN
- las Laoun	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) OTHER  )
1	Nil Conclusions of A.I.B.
	THE COURT IN CONCLUSION CONSIDERS THE CAUSE OF THE ACCIDENT OF LOCKHEEP 784L AS OBSCURE, AND LISTS THE FOLLOWING POSSIBLE EXPLANATIONS OF THE ACCIDENT IN ORDER OF PRIORITY; (1) HUMAN ERROR ON THE PART OF THE PILOT.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(11)TEMPORARY FUEL STARVATION AT LOW ALTITUDE.  (11)COMPLETE FUEL SHORTAGE.
	(IV) CONTRIBUTORY CAUSE; INCORRECT DECISION ON THE PART OF THE DATEOT ) TO PROCEED TO WINNIPEG AND NOT LAND BY DAYLIGHT EN ROUTE.
	CHECKED BY DATE )