

)))))))))))))))))))
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)
	Taxiing.	OR COMMANDING OFFICER'S REPORT: R170
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: MILLET
)	While taxiing across wind in a fairl	COMPOSITION:
)	high wind, a gust of wind struck the	TOALUEFLOWS
)	aircraft, causing it to veer into and	other
)	parked aircraft. The pilot was not taxiing fast, and he was unable to	other TCA/UET/COMMENDATIONS: 144/X7)
	control the swing of the aircraft, he	
(only 80 lbs. of air to apply brakes	with.
)	TATRIARY CAUSE.	<u>Nil</u>
)	Insufficient air brake pressure caus:	
	pilot to lose control of his aircraft)
)	11. athres	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)		Agradama Cantral Osciana tarta at 1
)		Aerodrome Control Officer instructed to have aircraft accompanied in to parking area by
)	\smile	airmen on wing tips in windy weather.
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	,
	A hoose made of the decision o	
,	A heavy gust of wind caused aircraft to swing into a parked aircraft while	RECORDED BY DATE
ļ <i>'</i>		
)	R.C.A.F. FORM LED BED. 267 101 Safe Failure	CHECKED BY DATE)
))))))))))))))))))))