

BUEV AN INCOME		<i>f</i>
DUTY ON WHICH ENGAGED: COURT OF INQUIRY,	INVESTIGATING OFFICER	
Gunnery exercise. OR COMMANDING OF	FFICER'S REPORT: R170	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:		
Pilot had landed after a gunnery COMPOSITION:	711/10/10/11/12/11	
exercise and was taxiing along the	•	
termac in front of the hangers. On		
attempting to turn, he was unable to do so due to low air pressure in the RECOMMENDATIONS	:	
brake bottle. He went off the taxi	-	
string into a snowbank, causing aircraft Nil		
to tilt forward damaging airscrew.		
Error in judgment on part of pilot in that		
he allowed aircraft to go off taxi strip into enow bank. Taxiing too (A) DISCIPLINARY	4-1-	
fast. (A) DISCIPLINARY	(B) TECHNICAL (C) OTHER	
11. actus (1)	ot's log book endorsed.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Aircraft tilted forward after going	RECORDED BY DATE	
into a snowbank .	DATE TO THE PARTY OF THE PARTY	
	CHECKED BY DATE	
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	