

| DUTY ON WHICH ENGAGED: Taxing.  | COURT OF INQUIRY. INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: |
|---|---|
| NATURE OF ACCIDENT AND STAGE OF FLIGHT:  After forced landing reference our E34 22-3-42 A/C was repaired at | DATE: COMPOSITION: TBC/ANT/XCM  |
| seene and was taxiing to take off   | to  |
| ) turn to airdrome when wheels broke ) ice in field and A/C nosed over.+                                    | RECOMMENDATIONS:  |
| due to strong tail wind and forward notion of A/C suddently ceasing.  |   |
| ) PRIMARY CAUSE:  |   |
| Poor surface on wedge A/C was taxiii Wheels of aircraft broke through ic                                    | ±g.   |
| )   | <b>8.</b>   |
| (10)  | ACTION TAKEN:  (A) DISCIPLINARY (E) TECHNICAL (C) OTHER                 |
| 1. 10. Bad Ground   | <u></u>   |
| ) SECONDARY CAUSE OR CONTRIBUTING FACTORS:  |   |
| Forward motion of aircraft sud-   |   |
| denly ceasing.  | RECORDED BY DATE  |
|   | CHECKED BY DATE   |
| ) ) ) ) ) ) ) <b>) ) ) ) ) )</b>  | , , , , , , , , , , , , , , , , , , ,                                   |