

Duty on Which engaged: Solo practice & sequences.	COURT OF INQUIRY, INVESTIGATING OFFICER  OR COMMANDING OFFICER'S REPORT:	09 2000 <b>3</b> 200
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Overshot landing strip, landing too fast with stick not full back, when brakes applied. Aircraft then nosed over,	DATE: LO/HTG/PSO/UEP COMPOSITION:	
	RECOMMENDATIONS:	
PRIMARY CAUSE: Inexperience, on part of pilot in that he landed too fast.	Nil	
(1) Occushet	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other	
	Paraded before Commanding Officer. Log Book en ed "Inexperience."	ndors-
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Aircraft nosed over on back.	RECORDED BY D	PATE
	CHECKED BY D	ATE