

1))))))))))))))))))	
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Engine assisted approaches. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Undershot aerdrome and struck boundary fence.	DATE: COMPOSITION:
)		RECOMMENDATIONS:
,		Nil
)	PRIMARY CAUSE: Pupil mis judged approach.)
	(3) cendristat	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Admonished, and instructed in corrective action which should have been taken.
)	CECONDADY GAUGE OF CONTRIBUTING FACTORS	
,	secondary cause or contributing factors: Failed to increase throttle to	
)	carry a/c over boundary fence.	RECORDED BY DATE
,		CHECKED BY DATE
))))))))))))))))))	