

OUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Solo flying practice.	OR COMMANDING OFFICER'S REPORT:
A/C stalled too high & landed heavily on airdrome, followed by severe ground loop. Port oleo	DATE: COMPOSITION:
eg collapsed.	RECOMMENDATIONS:
PRIMARY CAUSE:	
Hea vy landing. E rror in judgme nt.	
(H) Heavy	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER No disciplinary action was taken. Student given further dual instruction on landings.
evere ground loop to left causing out oleo leg to collapse. 34. UC Strain	RECORDED BY DATE
24. UC Wain	CHECKED BY DATE