

DUTY ON WHICH ENGAGED: Routine training flight. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced landing approach was made. Pupil was instructed to climb up again and at 500 ft. instructor closed throttle to make another forced landing. With nose down pupil proceeded to sideslip. Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSE ground on one wing tip and turned Primary Cause: Pailed to recover from side slip at safe height. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Disciplinary action is being taken against instructor A. fine of \$50,00 and endorsation made in the instructor's log book. RECORDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over. RECORDARY CAUSE OR CONTRIBUTING FACTORS: CHECKED BY DATE			
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced landing approach was made. Pupil was instructed to climb up again and at 500 ft. instructor closed throttle to make another forced landing. With nose down pupil proceeded to sideslip. Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSEground on one wing tip and turned over on its back. Primary Cause: ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Primary Cause: Primary Cause: Failed to recover from side slip at safe height. ACTION TAKEN: (A) Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book.	Routine training flight.	OR COMMANDING OFFICER'S REPORT:	
Forced landing approach was made. Pupil was instructed to climb up again and at 500 ft. instructor closed throttle to make another forced landing. With nose down pupil proceeded to sideslip. Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSE ground on one wing tip and turned over on its back. Primary Cause: ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.		11 A G 1 D C G 1 D C	
Pupil was instructed to climb up again and at 500 ft. instructor closed throttle to make another forced landing. With nose acompany pupil proceeded to sideslip. RECOMMENDATIONS: Instructor permitted this till 30feet off ground then tried to recover, aircraft struck primary Causeground on one wing tip and turned over on its back. Primary Cause: Pailed to recover from side slip at safe height. Action taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. Secondary Cause or Contributing factors: Wing tip touched ground and aircraft turned over. Date Da			
and at 500 ft. instructor closed throttle to make another forced landing. With nose down pupil proceeded to sideslip. Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSE ground on one wing tip and turned over on its back. Primary Cause: Primary Cause: Pailed to recover from side slip at safe height. Action taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor a.fine of \$50.00 and endorsation made in the instructor's log book. Secondary Cause or Contributing factors: Wing tip touched ground and aircraft turned over. Date Date			
to make another forced landing. With nose down pupil proceeded to sideslip. Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSE ground on one wing tip and turned over on its back. Primary Cause: Failed to recover from side slip at safe height. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Disciplinary action is being taken against instructor A. fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.	, -		
ACTION TAKEN: (A) Disciplinary Cause: (A) Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. Secondary cause or contributing factors: Wing tip touched ground and aircraft turned over.	_		
Instructor permitted this till 30feet off ground then tried to recover, aircraft struck PRIMARY CAUSE ground on one wing tip and turned over on its back. Primary Cause: Action taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor A. fine of \$50.00 and endorsation made in the instructor's log book. Secondary Cause or Contributing factors: Wing tip touched ground and aircraft turned over.	_		
ground then tried to recover, aircraft struck PRIMARY CAUSEground on one wing tip and turned over on its back. Primary Cause: ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Disciplinary action is being taken against instructor A. fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.			
Primary Cause: Primary Cause: Primary Cause: Pailed to recover from side slip at safe height. Action Taken: Action Taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. Secondary Cause or contributing factors: Wing tip touched ground and aircraft turned over. Action Taken: (B) Technical (C) Other Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book.	``		
Primary Cause: Failed to recover from side slip Action Taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. Secondary cause or contributing factors: Wing tip touched ground and aircraft turned over. Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book.	WA 1		
Primary Cause: Failed to recover from side slip Action Taken: Action Taken:			
Failed to recover from side slip at safe height. Action taken: (A) Disciplinary (B) Technical (C) Other Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.)		
Failed to recover from side slip at safe height. A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.	Primary Cause:		
Pailed to recover from side slip at safe height. Disciplinary action is being taken against instructor A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.)		
A.fine of \$50.00 and endorsation made in the instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.	_		_
instructor's log book. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.			T.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip touched ground and aircraft turned over.	19 Out of lecentral		
Wing tip touched ground and aircraft turned over.	, 17. 33	inducation of the opposit	
Wing tip touched ground and aircraft turned over.	SECONDARY CAUSE OR CONTRIBUTING FACTORS		
turned over.			
		RECORDED BY DATE	•
7 R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41 CHECKED BY DATE	turned over.		
7 R.C.A.F. FORM 120 REQ. 1247 10M-15-11-41 CHECKED BY DATE		CHECKED BY	-
	7 R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED RA DATE	
	· Control of the cont	and was a first for a first of the control of the c	