



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

R170

**Side slipping.**

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

11/02/70

**A/C stalled while sideslipping at too low an altitude outside solo area. Aircraft careened across a farmer's yard, knocking over a well pump, and finally crashed into a clump of trees.**

COMPOSITION:

RECOMMENDATIONS:

**Nil**

PRIMARY CAUSE:

~~A/C stalled and pupil failed to recover.~~

*COLLISIONS*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Disciplinary action taken against LAC Cobb was as follows: 7 days detention, 7 days C.B., and 5 hours punishment drill.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft crashed into a clump of trees.~~

RECORDED BY

DATE

CHECKED BY

DATE