

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Cross country navigation training.	OR COMMANDING OFFICER'S REPORT:
WITH AT AGREEM AND OTHER AT THEIR	Investigating Officer's Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT: The A/C, directly on its course, ha	
flown into the side of a hill at hig speed in level flight or in a shallo live; had caught fire on impact.	
Tilot failed to turn back when cloud	RECOMMENDATIONS:
Chanance at time of erach 800°.	
PRIMARY CAUSE:	
ither pilot tried to break cloud t	chinking.
e was over lower ground than he wa	
he A/C became iced up & lost heigh	
FLEW INTO GROUND	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
(20)	Conclusions of A.I.B.
	Agree with the finding of the investigation.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	The pilot was right on his alternative track when accident occurred.
	DATE.
FIRE IN CRASH. (24)	RECORDED BY DATE