

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																					
CAUSES OF ACCIDENTS																																																																																																			
UNIT										COM.										PLACE																																																																															
133 (F) Sqdn.										# 4										Lethbridge Aerodrome																																																																															
Lethbridge, Alta.																				DATE 30-6-42 TIME 1630																																																																															
A/C TYPE										No.										H.Q. FILE 1100-53-79																																																																															
Hurricane										5379										CRASH CAT. C14																																																																															
NAME										RANK No.										DUTY																																																																															
Collins, E.J.										SGT R125050 PP										INJURIES																																																																															
																				SERIOUS																																																																															
																				FATAL INJURY																																																																															
																				CARD SERIAL No.																																																																															
TYPE A/F & ENGINE										No.										EXTENT OF DAMAGE																																																																															
Hurricane										5379										Not known																																																																															
Merlin										A236/5379										Not known																																																																															
SIGNAL No. & DATE										UNIT No. & DATE										COM. No. & DATE																																																																															
Nil										30-6																																																																																									
NATURE OF ACCIDENT																																																																																																			

CAUSES
 STAGE OF FLIGHT
 MISCELLANEOUS
 HAND Q
 INSTS.
 WEATHER
 DRINKS
 ALG SURF
 OTHER
 UNDTD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATIONARY
 FATAL
 INJ.
 BRO.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Local flying.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot undershot while executing a forced landing on aerodrome due to reputed engine failure. Aircraft hit a fence and crashed.

COMPOSITION:

L. / psc

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Reputed engine failure.~~

3 **UNDERSHOT**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's log book endorsed "Gross Carelessness."

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft hit a fence and crashed.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____