

DUTY ON WHICH ENGAGED: Landing practice.	COURT OF INQUIRY, INVESTIGATING OFF OR COMMANDING OFFICER'S REPORT:	ICER	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot held off when landing at	DATE: LH	R17	70
30' in the air, the aircraft stalled, and landed heavily,	<u> </u>		3
bending the bottom port Longeron.	RECOMMENDATIONS:)
PRIMARY CAUSE: Error or judgment on the part)
of the pupil. H. I sauf	ACTION TAVEN.		
n or sainly	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) Further instruction in lar)
	ruremer inscruection in lan	mings.)
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft made a heavy landing.		RECORDED BY	DATE
)
R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41		CHECKED BY)))))