

| DUTY ON WHICH ENGAGED: | COURT OF INQUIRY, INVESTIGATING OFFICER | |
|---|--|---|
| Local solo. | OR COMMANDING OFFICER'S REPORT: | |
| Forced landing approach practice. | / / / R170 | |
| NATURE OF ACCIDENT AND STAGE OF FLIGHT: | DATE: LFM/HOP/YCVE/FS/PM//H/IL | |
| Pupil practicing forced landing | COMPOSITION: | |
| approach opened throttle at 500 | | |
| feet, engine sputtered and failed | | |
| to pick up, pupil carried out | | |
| unsuccessful forced landing. | RECOMMENDATIONS: | |
| Overshot field. Kailed to clear engine | | |
| | | _ |
| Error in judgment | | |
| 17. Farced Landing | ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil | - |
| | | |
| SECONDARY CAUSE OR CONTRIBUTING FACTORS: Forced landing and overshooting. | RECORDED BY DATE | |
| 26. Engine trouble - acco | BENUT. | |
| \mathscr{I} | | , |
| R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41 | CHECKED BY DATE | - |
| | | |

)))))))))))))))))))))