

DUTY ON WHICH ENGAGED:

A/C test.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Landed crosswind on runway due to repairs of proper runway, gust of wind caused A/C to ground loop.

DATE:

LS/PSS/2/1000 C

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Swing

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Z

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____