

	CHEC	DKED BY DATE	
styled in gliding turned	RECC	DRDED BY DATE	<u> </u>
PRIMARY CAUSE: Export of Indeport. Aut of Control	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil.		
NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C stalled and spiralled into ground. Student applied too much rudder on entering turn, the nose and inner wing dropped and he endeavored to bring them up by easing the control column back and at the same time holding off bank.	RECOMMENDATIONS:		
	DATE: LOCALISTICS COMPOSITION:		
Duty on Which Engaged: Day routine training.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	D-14	