

| ) DUTY ON WHICH ENGAGED:  | COURT OF INQUIRY, INVESTIGATING OFFICER )   |
|---|---|
| ) Dusk patrol.  | OR COMMANDING OFFICER'S REPORT:  INVESTIGATING OFFICER'S REPORT   |
| ) NATURE OF ACCIDENT AND STAGE OF FLIGHT:                         | DATE: 16-10-42.   |
| Engine failure. Pilot bailed out ) at approximately 1000 feet and | COMPOSITION: F/O Robinson, E.L. RCAF Station, Torbay.   |
| landed safely in woods.   | RECOMMENDATIONS: IMP/1/2/2 3/20/10/1  |
| )   | NiL.  |
| ) DRIMARY CAUCE   | )   |
| ) PRIMARY CAUSE: Epon the information available.                  | )   |
| and due to the total demolishment                                 | )   |
| for the stoppage of the A/C engine                                | ACTION TAKEN:   |
| \ can be determined.  | (A) Disciplinary (B) Technical (C) Other NiL.   |
| M N / another   | CONCLUSIONS OF A.I.B.   |
| Mut of comme  | The cause of the engine failure cannot be determined  |
|   | but the possibility that it was due to mechanical breakdown of the engine cannot be dismissed. There is |
| ) SECONDARY CAUSE OR CONTRIBUTING FACTORS:                        | evidence at least of a glycol leak.   |
| Engine Should - Accid   | Lent RECORDED BY DATE   |
| 66)   | RECORDED BY DATE  |
|   | CHECKED BY DATE )   |
|   |   |