OSO LE NE	OTHERS	AIRFRAME	FAILUF		ENGIN		2 1 12 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1
UNIT 11 E		PLACE Sare	abe Stat	ion Co.	H.Q. FILE 1100	-44 TIME 1240 -44-56	1 1 / .601
A/C TYPE	2 1,12002020	No. 4456		\SH	SE ME	DAY NIGHT	1 S MERT
<u>E Tee</u>	t Finch 11	RANK NO.	DUTY	INJUE		SERIOUS	DE ORK
L E S O	rand, J.L. La	R164538	3 PP	Mál.		CARD SERIAL NO.	S A RIPORT
TYPE A/F & ENGINE	No. extent of DAMAGE	REPORT SERIAL FORM No.	DATE	INST. NIGHT	ON TYPE	TOTAL LAST 6 MOS	
	6042/1351 HiL.						
Kinner							

DUTY ON WHICH ENGAGED:	COURT OF INCHIBY INVESTIGATION OF THE P
Sequences 7 9 10 12 15.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: This student became lost and	DATE: COMPOSITION: FRPCN/WVZ D-14
landed during a snow storm in a field in rough terrain. The A/C did not stop before going through	7 /
a fence.	RECOMMENDATIONS:
ODIMARY CAUCE	Students to stay within sight of aerodrome in doubtful weather.
PRIMARY CAUSE: Inexperience. Student became lost when it started to snow.	
(CALLISIONS	
φ.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	The book of Second 197
	Log book endorsed "Inexperience".
	Log book endorsed "Inexperience".
· week	Log book endorsed "Inexperience".
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Poor visibility, A/C collided	Log book endorsed "Inexperience".
	RECORDED BY DATE