



DUTY ON WHICH ENGAGED:

Ferry flight

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

After landing and while taxiing in a strong gusty wind through snow drifted on runway, the A/C nosed up, causing damage to propellor only.

DATE:

COMPOSITION:

TBG/ANT/PCT/X GA/WWO

RECOMMENDATIONS:

PRIMARY CAUSE:

~~1. Bad surface of aerodrome.~~

10. Bad Ground

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(C) Airport has been declared unserviceable until further notice.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Nosing up. Snow drifted on runway.~~

RECORDED BY

DATE

CHECKED BY

DATE