

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT 10 E.F.T.S.		COM.		PLACE $\frac{1}{2}$ mile south of				DATE 12-1-43		TIME 1400			
Pendleton, Ont.		# 3		St. Pasquel, Ontario.				H.Q. FILE		1100-58-95			
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY NIGHT			
Tiger Moth		5895		C 2		x				x			
NAME			RANK	No.	DUTY	INJURIES			SERIOUS				
Smith, H.W.			SGT	R131090	P.	Nil			FATAL	INJURY			
Morrell, W.			LAC	1578517	PP	Nil							
									CARD SERIAL NO.				
									✓				
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS						
T. Moth		5895	Slight				INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.
G. Major		7821/85682	Slight							DUAL	SOLO	DUAL	SOLO
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE			
197		13-1											
NATURE OF ACCIDENT													

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

TECH.  
DISOB.  
NEG'NCE  
INEXP'NCE  
MISCEL.  
INSTRUCT.  
FLT. CONTR.  
OTHERS  
PRIMARY  
FL. CONTRS.  
MOV. SURFS.  
STAB. SURFS.  
W. STRUTS  
LAND. GEAR  
FLOATS  
FUSE. OR HULL  
TAIL SKID OR W.  
ENGINE MOUNT.  
MISCEL.  
UND/TD  
PRIMARY  
FUEL SYS.  
COOL SYS.  
IGNIT. SYS.  
LUB'N SYS.  
ENG. STR.  
AIRSCREW A.  
ENG. CONTRS.  
MISCEL.  
UND/TD  
PRIMARY  
HAND Q.  
INSTS.  
WEATHER  
DRKNS.  
ALG'S SURF.  
OTHER  
UND/TD  
PRIMARY  
TAXING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INI.  
3RD.

DUTY ON WHICH ENGAGED:

Demonstrating forced landings.

Sequences 1C-3-6-7-10-17.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot misjudged height, came down too low and wheels struck soft snow overturning A/C.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION: *ILCG/PSJ*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~39. Flattening out too soon.~~

*4. Heavy*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor admonished and logged and an endorsement in red was placed in instructor's log book.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C hit soft snow and turned over on its back.~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_