	PILOT	OTHERS	en in his			PAILUF		JAD PRIM	EN G		CHE KIRS		Str. Str.
				AUSE	5 0		CIDEN		ENGINE FAILURE				
UN	UNIT 34 E.F.T.S.				PLACE								
A.s	sinibo	ia, Sask.	# 4	Home Aerodrome					<u> </u>				MENTHE WEATH
TY		r Moth		No.	1165	CA.		c _	SE ME	0/	AT NI	IGH I	101/37
-	Tiger Moth			1139 - D C 5					RIES SERIOUS				S C E DATE
1-						1				F	ATAL IN	VAULV	
-		son, W.A.		LAC 1455189 PP Nil 1139						m	'  Z   / 🎺 /		
u	Alrei	raft 1165	unoccup.	pied					o o o				
2			-		•							(1)	
5											CARE SERIAL	,	121/32
2 2 1		_										,	© U <sub>M</sub> O'
												,	S O NO S SEIMA
10 11	TVDE A/E				T SERIAI			ноиг	RS FLOWN	BY PILC	SERIAL	,	S S S S S S S S S S S S S S S S S S S
i i	TYPE A/F	No.	EXTENT OF DAMAGE			DATE	INST		S FLOWN	1	DTS	No.	S S S S S S S S S S S S S S S S S S S
i i		1165	extent of damage Slight			DATE	INST. N	IGHT		1	DTS	No.	LS S I S I S I S I S I S I S I S I S I S
T.	Moth Major	<b>1165</b> 7167/869	of DAMAGE Slight			DATE	INST. N	IGHT	ON TYPE	то	DTS	LAST TO MOS.	S A C STAC
i i	Moth Moth Moth Moth	1165 7167/869 1139	of DAMAGE Slight 87 NiL. light			DATE	INST	IGHT	ON TYPE	то	DTS	LAST 16 MOS.	STAGE STAGE
T. G.T.	Moth Major	1165 7167/869 1139 2197/858	of DAMAGE Slight 87 NiL. light	REPOR	No.	DATE No & DAT		IGHT	ON TYPE	то	DTS	LAST TO G MOS.	S A D S S T A C E C C C C C C C C C C C C C C C C C

DUTY ON WHICH ENGAGED:  Solo practice.  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Aircraft 1139 taxied into aircraft 1165.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:  DATE:  COMPOSITION:  D-14
·	RECOMMENDATIONS:
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Disciplianry action taken against student concerned.  Students warned that there is no excuse for a taxying accident and that extreme care and vigilance must always be exercised.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Careless tax in by student.	RECORDED BY DATE
· · · · · · · · · · · · · · · · · · ·	CHECKED BY DATE