

PILOT		AIRFRAME FAILURE												ENGINE FAILURE							
		CAUSES OF ACCIDENTS																			
UNIT 11 E.F.T.S.			COM. 3			PLACE M.A.			DATE 25-2-43		TIME 1630										
Cap de la Madeleine									H.O. FILE 1100-46-31												
A/C TYPE Fleet Finch 11			No. 4631			CRASH CAT. D 1/4			SE X		ME		DAY X		NIGHT						
NAME Cohen, B.				RANK Lac.		No. R154133		DUTY PP		INJURIES Nil.				SERIOUS							
										FATAL				INJURY							
														CARD SERIAL No.							
														V							
TYPE A/F & ENGINE			No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS								
Finch 4631 Slight													INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.		
Kinner 6052/1390 Nil.													DUAL SOLO		DUAL SOLO						
SIGNAL No. & DATE			UNIT No. & DATE			COM. No. & DATE			REPORT			FILE		DATE							
NATURE OF ACCIDENT																					

JUN 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS

STAGE OF FLIGHT

CAUSES

TECH. 6
DISOB. 6
NEG-NCE 6
INEXP-NC 6
MISCEL. 6
INSTRUCT. 6
FLT CONTR. 6
OTHERS 6
PRIMARY 6
FL. CONTR. 6
MOV. SURFS. 6
STAB. SURFS. 6
W. STRUTS 6
LAND. GEAR 6
FLOATS 6
FUZE. OR HULL 6
TAIL SKID OR W. 6
ENGINE MOUNT. 6
MISCEL. 6
UND TD 6
PRIMARY 6
FUEL SYS. 6
COOL SYS. 6
IGNIT. SYS. 6
LUB'N SYS. 6
ENG. STR. 6
AIRSCREW A. 6
ENG. CONTRS. 6

UND TD
PRIMARY
HAND O.
INSTS.
WEATHER
DRAINS.
ALG SURF.
OTHER
UND TD
PRIMARY
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD INJ.
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32

DUTY ON WHICH ENGAGED:

Routine training flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

When landing, student flew into ground and bounced badly. He opened throttle to correct bounce, but engine failed to respond and A/C landed heavily breaking oleo leg.

DATE:

COMPOSITION:

LA/PSM/2000

RECOMMENDATIONS:

PRIMARY CAUSE:

40. Heavy landing-Flying into ground.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Inexperience".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Inexperience of pilot.

RECORDED BY

DATE

CHECKED BY

DATE